

<b>Supervision</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Adults present	90	50	A	F
Easily viewed	100	87	A+	B+
Crawl spaces	95	69	A	D+
Supervision rules posted	24	17	F	F
<b>Overall Grade: Supervision</b>			<b>B</b>	<b>D+</b>
<b>Age-Appropriate Design</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Had separate areas	55	33	F	F
Signage for age group provided	10	15	F	F
Provided change of direction	100	100	A+	A+
Had guardrails	100	81	A+	B-
Prevented climbing outside the structure	95	78	A	C+
Supporting structure prevented climbing on	95	87	A	B+
<b>Overall Grade: Age - Appropriate Design</b>			<b>B</b>	<b>C+</b>
<b>Fall Surfacing</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Suitable materials provided	95	87	A	B+
Heights of equipment 8 feet or lower	NA	86	NA	B
Appropriate depth of loose fill	71	48	C-	F
Six foot use zone had appropriate surface	95	55	A	F
Concrete footings were covered	100	96	A+	A
Free of foreign objects	86	100	B	A+
<b>Overall Grade: Fall Surfacing</b>			<b>B+</b>	<b>B-</b>
<b>Equipment Maintenance</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Free of broken parts	100	78	A+	C+
Free of missing parts	95	91	A	A-
Free of protruding bolts	100	96	A+	A
Free of noticeable gaps	95	96	A	A
Free of head entrapments	95	86	A	B
Free of rust	95	87	A	B+
Free of splinter	NA	NA	NA	NA
Free of cracks/holes	100	95	A+	A
<b>Overall Grade: Equipment Maintenance</b>			<b>A</b>	<b>B+</b>


<b>Playground Equipment Profile*</b>		
<b>Year of installation</b>	<b>2004</b>	
Pre 1980	0%	
1981-1990	9%	
1991-1994	22%	
1995-1997	30%	
1998-present	34%	
Not available	4%	
<b>Kinds of Equipment**</b>	<b>2000</b>	<b>2004</b>
Slides	95%	86%
Swings	100%	61%
Horizontal ladders	52%	48%
Sliding poles	48%	30%
Chinning bars	5%	9%
Seesaws	0%	0%
Merry-go-rounds	0%	0%
Geodesic domes	0%	0%
<p>* The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.</p> <p>** The numbers in these columns reflect percentages of equipment pieces were found.</p> <p>Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59&gt;</p>		

# Arizona's Park Grade:

**2000**  
**B+**

**2004**  
**C+**

Comments



The National Program  
For Playground Safety  
America's  
Playgrounds  
Safety  
Report Card  
2004

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

National Program for Playground Safety  
School of Health, Physical Education, and Leisure Services  
University of Northern Iowa  
Cedar Falls, IA 50614-0618

800/554-PLAY (7529)  
Fax: 319/273-7308  
e-mail: [playground-safety@uni.edu](mailto:playground-safety@uni.edu)

World Wide Web:  
<http://www.playgroundsafety.org>

*America's playgrounds  
Make them safe*

Arizona Park