


<b>Supervision</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Adults present	95	62	A	D-
Easily viewed	100	88	A+	B+
Crawl spaces	99	69	A	D+
Supervision rules posted	12	8	F	F
<b>Overall Grade: Supervision</b>			<b>B+</b>	<b>D+</b>
<b>Age-Appropriate Design</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Had separate areas	52	31	F	F
Signage for age group provided	9	14	F	F
Provided change of direction	98	86	A	B
Had guardrails	95	85	A	B
Prevented climbing outside the structure	97	81	A	B-
Supporting structure prevented climbing on	96	84	A	B
<b>Overall Grade: Age - Appropriate Design</b>			<b>B-</b>	<b>C</b>
<b>Fall Surfacing</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Suitable materials provided	94	89	A	B+
Heights of equipment 8 feet or lower	NA	97	NA	A
Appropriate depth of loose fill	64	50	D	F
Six foot use zone had appropriate surface	94	49	A	F
Concrete footings were covered	99	99	A	A
Free of foreign objects	91	97	A-	A
<b>Overall Grade: Fall Surfacing</b>			<b>B+</b>	<b>B-</b>
<b>Equipment Maintenance</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Free of broken parts	88	89	B+	B+
Free of missing parts	91	92	A-	A-
Free of protruding bolts	98	97	A	A
Free of noticeable gaps	92	91	A-	A-
Free of head entrapments	92	81	A-	B-
Free of rust	93	91	A-	A-
Free of splinter	92	93	A-	A-
Free of cracks/holes	100	99	A+	A
<b>Overall Grade: Equipment Maintenance</b>			<b>A-</b>	<b>A-</b>

<b>Playground Equipment Profile*</b>		
<b>Year of installation</b>	<b>2004</b>	
Pre 1980	3%	
1981-1990	7%	
1991-1994	26%	
1995-1997	36%	
1998-present	30%	
Not available	8%	
<b>Kinds of Equipment**</b>	<b>2000</b>	<b>2004</b>
Slides	44%	89%
Swings	79%	52%
Horizontal ladders	53%	46%
Sliding poles	97%	34%
Chinning bars	33%	18%
Seesaws	11%	8%
Merry-go-rounds	7%	0%
Geodesic domes	13%	3%
<p><sup>5</sup> * The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.</p> <p>** The numbers in these columns reflect percentages of equipment pieces were found.</p> <p>Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59&gt;</p>		



Comments

---

The National Program  
For Playground Safety  
**America's  
Playgrounds  
Safety  
Report Card  
2004**

---

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

**National Program for Playground Safety  
School of Health, Physical Education, and Leisure Services  
University of Northern Iowa  
Cedar Falls, IA 50614-0618**

**800/554-PLAY (7529)  
Fax: 319/273-7308  
e-mail: [playground-safety@uni.edu](mailto:playground-safety@uni.edu)**

**World Wide Web:  
<http://www.playgroundsafety.org>**

*America's playgrounds  
Make them safe*

---

**State of  
Arizona**