

<b>Supervision</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Adults present	67	NA	D+	NA
Easily viewed	100	100	A+	A+
Crawl spaces	60	100	D-	A+
Supervision rules posted	20	10	F	F
<b>Overall Grade: Supervision</b>			<b>C-</b>	<b>B</b>
<b>Age-Appropriate Design</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Had separate areas	100	NA	A+	NA
Signage for age group provided	0	0	F	F
Provided change of direction	47	70	F	C-
Had guardrails	33	100	F	A+
Prevented climbing outside the structure	60	90	D-	A-
Supporting structure prevented climbing on	60	90	D-	A-
<b>Overall Grade: Age - Appropriate Design</b>			<b>D</b>	<b>B-</b>
<b>Fall Surfacing</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Suitable materials provided	53	100	F	A+
Heights of equipment 8 feet or lower	NA	100	NA	A+
Appropriate depth of loose fill	43	80	F	B-
Six foot use zone had appropriate surface	47	70	F	C-
Concrete footings were covered	67	100	D+	A+
Free of foreign objects	100	100	A+	A+
<b>Overall Grade: Fall Surfacing</b>			<b>D+</b>	<b>A-</b>
<b>Equipment Maintenance</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Free of broken parts	93	80	A-	B-
Free of missing parts	80	100	B-	A+
Free of protruding bolts	87	90	B	A-
Free of noticeable gaps	93	80	A-	B-
Free of head entrapments	100	80	A+	B-
Free of rust	20	60	F	D-
Free of splinter	80	NA	B-	NA
Free of cracks/holes	100	89	A+	B+
<b>Overall Grade: Equipment Maintenance</b>			<b>B</b>	<b>B</b>


<b>Playground Equipment Profile*</b>		
<b>Year of installation</b>	<b>2004</b>	
Pre 1980	10%	
1981-1990	20%	
1991-1994	20%	
1995-1997	40%	
1998-present	30%	
Not available	NA	
<b>Kinds of Equipment**</b>	<b>2000</b>	<b>2004</b>
Slides	0%	0%
Swings	40%	70%
Horizontal ladders	80%	80%
Sliding poles	33%	40%
Chinning bars	60%	70%
Seesaws	14%	0%
Merry-go-rounds	0%	0%
Geodesic domes	13%	40%
* The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.		
** The numbers in these columns reflect percentages of equipment pieces were found.		
Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59>		

# Hawaii's School Grade:

**2000**  
**C+**

**2004**  
**B**

## Comments



# The National Program For Playground Safety America's Playgrounds Safety Report Card 2004

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

National Program for Playground Safety  
School of Health, Physical Education, and Leisure Services  
University of Northern Iowa  
Cedar Falls, IA 50614-0618

800/554-PLAY (7529)

Fax: 319/273-7308

e-mail: [playground-safety@uni.edu](mailto:playground-safety@uni.edu)

World Wide Web:  
<http://www.playgroundsafety.org>

*America's playgrounds  
Make them safe*

# Hawaii

# School