

<b>Supervision</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Adults present	83	100	B-	A+
Easily viewed	100	100	A+	A+
Crawl spaces	100	77	A+	C+
Supervision rules posted	13	26	F	F
<b>Overall Grade: Supervision</b>			<b>B</b>	<b>B</b>
<b>Age-Appropriate Design</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Had separate areas	16	4	F	F
Signage for age group provided	7	0	F	F
Provided change of direction	93	100	A-	A+
Had guardrails	94	97	A	A
Prevented climbing outside the structure	73	97	C-	A
Supporting structure prevented climbing on	100	94	A+	A
<b>Overall Grade: Age - Appropriate Design</b>			<b>C+</b>	<b>B</b>
<b>Fall Surfacing</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Suitable materials provided	81	81	B-	B-
Heights of equipment 8 feet or lower	NA	87	NA	B+
Appropriate depth of loose fill	54	87	F	B+
Six foot use zone had appropriate surface	77	77	C+	C+
Concrete footings were covered	81	100	B-	A+
Free of foreign objects	94	94	A	A
<b>Overall Grade: Fall Surfacing</b>			<b>C+</b>	<b>B+</b>
<b>Equipment Maintenance</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Free of broken parts	100	100	A+	A+
Free of missing parts	87	97	B+	A
Free of protruding bolts	71	97	C-	A
Free of noticeable gaps	87	84	B+	B
Free of head entrapments	87	87	B+	B+
Free of rust	97	100	A	A+
Free of splinter	100	100	A+	A+
Free of cracks/holes	100	100	A+	A+
<b>Overall Grade: Equipment Maintenance</b>			<b>B</b>	<b>A</b>

<b>Playground Equipment Profile*</b>		
<b>Year of installation</b>	<b>2004</b>	
Pre 1980	7%	
1981-1990	29%	
1991-1994	21%	
1995-1997	0%	
1998-present	45%	
Not available	7%	
<b>Kinds of Equipment**</b>	<b>2000</b>	<b>2004</b>
Slides	97%	100%
Swings	97%	90%
Horizontal ladders	58%	33%
Sliding poles	55%	42%
Chinning bars	23%	4%
Seesaws	13%	13%
Merry-go-rounds	19%	13%
Geodesic domes	7%	3%
<p>* The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.</p> <p>** The numbers in these columns reflect percentages of equipment pieces were found.</p> <p>Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59&gt;</p>		

# Oklahoma's Park Grade:

**2000**

**B-**

**2004**

**B+**



Comments

---

The National Program  
For Playground Safety  
America's  
Playgrounds  
Safety  
Report Card  
2004

---

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

National Program for Playground Safety  
School of Health, Physical Education, and Leisure Services  
University of Northern Iowa  
Cedar Falls, IA 50614-0618

800/554-PLAY (7529)  
Fax: 319/273-7308  
e-mail: [playground-safety@uni.edu](mailto:playground-safety@uni.edu)

World Wide Web:  
<http://www.playgroundsafety.org>

*America's playgrounds  
Make them safe*

---

Oklahoma  
Park