

<b>Supervision</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Adults present	67	83	D+	B-
Easily viewed	100	100	A+	A+
Crawl spaces	100	62	A+	D-
Supervision rules posted	0	4	F	F
<b>Overall Grade: Supervision</b>			<b>B-</b>	<b>C</b>
<b>Age-Appropriate Design</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Had separate areas	67	NA	D+	NA
Signage for age group provided	0	NA	F	NA
Provided change of direction	95	100	A	A+
Had guardrails	89	95	B+	A
Prevented climbing outside the structure	90	100	A-	A+
Supporting structure prevented climbing on	100	95	A+	A
<b>Overall Grade: Age - Appropriate Design</b>			<b>B-</b>	<b>A</b>
<b>Fall Surfacing</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Suitable materials provided	70	90	C-	A
Heights of equipment 8 feet or lower	NA	86	NA	B
Appropriate depth of loose fill	39	67	F	D+
Six foot use zone had appropriate surface	65	86	D	B
Concrete footings were covered	42	95	F	A
Free of foreign objects	100	95	A+	A
<b>Overall Grade: Fall Surfacing</b>			<b>C-</b>	<b>B+</b>
<b>Equipment Maintenance</b>	<b>2000 %</b>	<b>2004 %</b>	<b>2000 Grade</b>	<b>2004 Grade</b>
Free of broken parts	80	95	B-	A
Free of missing parts	65	100	D	A+
Free of protruding bolts	75	100	C	A+
Free of noticeable gaps	100	91	A+	A-
Free of head entrapments	75	86	C	B
Free of rust	95	95	A	A
Free of splinter	88	100	B+	A+
Free of cracks/holes	100	100	A+	A+
<b>Overall Grade: Equipment Maintenance</b>			<b>B</b>	<b>A</b>

<b>Playground Equipment Profile*</b>		
<b>Year of installation</b>	<b>2004</b>	
Pre 1980	14%	
1981-1990	43%	
1991-1994	14%	
1995-1997	0%	
1998-present	52%	
Not available	NA	
<b>Kinds of Equipment**</b>	<b>2000</b>	<b>2004</b>
Slides	30%	95%
Swings	25%	76%
Horizontal ladders	89%	71%
Sliding poles	61%	67%
Chinning bars	70%	50%
Seesaws	16%	24%
Merry-go-rounds	25%	20%
Geodesic domes	37%	43%
<p>* The number in these columns indicates the percentages of the year of installation. These may contain a combination of different installation years at each playground site. NA represents percentages that are not available.</p> <p>** The numbers in these columns reflect percentages of equipment pieces were found.</p> <p>Grading Scale: A=90-100 B=80-89 C=70-79 D=60-69 F=59&gt;</p>		


# Oklahoma's School Grade:

**2000**

**B-**

**2004**

**B+**



Comments

---

The National Program  
For Playground Safety  
America's  
Playgrounds  
Safety  
Report Card  
2004

---

The National Program for Playground Safety is housed at the University of Northern Iowa. For additional information about playground safety, contact the National Program for Playground Safety at the following address:

National Program for Playground Safety  
School of Health, Physical Education, and Leisure Services  
University of Northern Iowa  
Cedar Falls, IA 50614-0618

800/554-PLAY (7529)  
Fax: 319/273-7308  
e-mail: [playground-safety@uni.edu](mailto:playground-safety@uni.edu)

World Wide Web:  
<http://www.playgroundsafety.org>

*America's playgrounds  
Make them safe*

**Oklahoma  
School**